

MONTAGEANLEITUNG

 MONTAGEANLEITUNG
 ASSEMBLY INSTRUCTION
 DE INSTRUCTIE VAN DE ASSEMBLAGE
 ISTRUZIONE DELL'ASSEMBLEA
 INSTRUCCIÓN DE ASAMBLEA
 INSTRUCTION DE MONTAGE
 NÁVOD K MONTÁŽI
 MONTERINGSANVISNING

 MONTAJ TALIMATI
 ASENNUSOHJE
 BRUGSANVISNING
 BRUKSANVISNING
 UPUTE ZA MONTÁŽU
 NAVODILA ZA MONTAŽO
 SZERELÉSI ÚTMUTATÓ
 INSTRUCTIUNI DE MONTAJ



Modell-Nr.

12170

Friedrich Küpper GmbH
 Friedrich-Küpper-Weg
 54570 Berlingen
 Deutschland

Telefon +49 (0) 65 91 - 95 42 0
 Telefax +49 (0) 65 91 - 95 42 17
 E-Mail info@friedrich-kuepper-gmbh.de
 Internet www.friedrich-kuepper-gmbh.de

ART.-NR. FRONT KORPUS

12171 Grün Silber

12172 Rot (ähnl. RAL 3002) Silber

12174 Blau Silber

12177 Ultramarinblau (RAL 5002) Silber

12176 Silber Schwarz

EINZELTEILE / PIECES

A

1x

772 mm x 475 mm



B

1x

772 mm x 475 mm



F

2x

645 mm x 450 mm



K

2x


403 mm x 468 mm



L

2x

400 mm x 25 mm



C

1x

1570 mm x 473 mm



D

1x


1570 mm x 473 mm



E

1x

1500 mm x 480 mm



Y

1x

1700 mm x 600 mm



H

6x


450 mm x 445 mm



I

6x


470 mm x 130 mm



J

6x

450 mm x 120 mm




X

6x




450 mm x 20 mm




BEUTELINHALT / BAG CONTENT

 8x 5,5x19 mm	 12x KU 4,2x13 mm	 24x M5x10 mm	 24x ø 5,3 mm	 24x M5	 48x M4 x 10 mm
 48x M4	 2x M6x16 mm	 2x ø 6,4 mm	 2x M6	 2x 6x12 mm	 2x
 2x	 2x	 4x	 4x	 4x M8	 6x


BENÖTIGTES WERKZEUG / NEEDED TOOLS

1  PH 1 x 100 PH 2 x 100 Schlitz 6,5 x 150	2  SW 7 SW 8 SW 10	3  4 mm
4 	5 	6  5 mm
7 	8 	


1.




2. WICHTIG / IMPORTANT




3. WICHTIG / IMPORTANT



4.  4x M5  4x M5x10  4x 5,3 MM




5.




6.  4x M5  4x M5x10  4x 5,3 MM  2 SW 8  1 PH 2x100



7.




8.



ZU SCHRITT 4. / IN ADDITION TO STEP 4.


②  SW 8 ①  PH 2x100




9. WICHTIG / IMPORTANT



10.  6x M5  6x M5 x 10  6x 5,3 MM ②  SW 8 ①  PH 2x100



11.  6x M5  6x M5 x 10  6x 5,3 MM ②  SW 8 ①  PH 2x100



12.

4x M8


4x



4x



5



13.

4x M5

4x



4x



M5 x 10

4x 5,3 mm

2




SW 8

1




PH 2 x 100




14.



15.





16.



17.



18.




19.




20.

2x M6 2x M6 x 16 2x 6,4 mm ② SW10 ⑥




21.

2x 2x




22.

⑧ 6x CR




23.

⑧ 6x CL




24. 12x M4 12x M4 x 10

②  SW7 ①  PH1 x 100




25. 36x M4 36x M4 x 10


②  SW7 ①  PH1 x 100




26.



27.



28.



29.


12x KU 4,2x13 6x  ①  PH2x100



30.



31.





Modell-Nr.

12170